




IMPORTANT: LINTELS MUST BE PROTECTED AGAINST COROSION BY PRIMER, HOT-DIP GALVANIZATION, OR BE MADE OF STAINLESS STEEL.




04 SCALE: 1:5


CUT OR COMPLETE BLOCK. DEPENDING ON THE DIMENSIONS OF THE OPENING.



03 SCALE: 1:5



02 SCALE: 1:5



01 SCALE: 1:25